




Figure 6  
Alternative 4 - Plan View



cross dike



excavated channels



area inundated by  
this alternative



Aerial Photos from WDNR (2000)

